

## INSTRUCTIONS FOR REPLACING THE PATHFINDER® II VALVE ASSEMBLY

**Important Note: Before removing the Valve Assembly, release all air pressure from the Pneumatic Heel Spring.**

Using a 3/8" thin-walled socket wrench:

1. Remove the old Valve Assembly.
2. Install the replacement Valve Assembly.
3. Tighten the replacement Valve Assembly to 50 inch-pounds.



**OHIO WILLOW WOOD**

*free the body...free the spirit®*

15441 Scioto Darby Road  
Mt. Sterling, OH 43143

phone 740.869.3377 / 800.848.4930 / fax 740.869.4374

PN-1772-B 1 NOV 2005

[www.owwco.com](http://www.owwco.com)

## INSTRUCTIONS FOR REPLACING THE PATHFINDER® II VALVE ASSEMBLY

**Important Note: Before removing the Valve Assembly, release all air pressure from the Pneumatic Heel Spring.**

Using a 3/8" thin-walled socket wrench:

1. Remove the old Valve Assembly.
2. Install the replacement Valve Assembly.
3. Tighten the replacement Valve Assembly to 50 inch-pounds.



**OHIO WILLOW WOOD**

*free the body...free the spirit®*

15441 Scioto Darby Road  
Mt. Sterling, OH 43143

phone 740.869.3377 / 800.848.4930 / fax 740.869.4374

PN-1772-B 1 NOV 2005

[www.owwco.com](http://www.owwco.com)

## INSTRUCTIONS FOR REPLACING THE PATHFINDER® II VALVE ASSEMBLY

**Important Note: Before removing the Valve Assembly, release all air pressure from the Pneumatic Heel Spring.**

Using a 3/8" thin-walled socket wrench:

1. Remove the old Valve Assembly.
2. Install the replacement Valve Assembly.
3. Tighten the replacement Valve Assembly to 50 inch-pounds.



**OHIO WILLOW WOOD**

*free the body...free the spirit®*

15441 Scioto Darby Road  
Mt. Sterling, OH 43143

phone 740.869.3377 / 800.848.4930 / fax 740.869.4374

PN-1772-B 1 NOV 2005

[www.owwco.com](http://www.owwco.com)

## INSTRUCTIONS FOR REPLACING THE PATHFINDER® II VALVE ASSEMBLY

**Important Note: Before removing the Valve Assembly, release all air pressure from the Pneumatic Heel Spring.**

Using a 3/8" thin-walled socket wrench:

1. Remove the old Valve Assembly.
2. Install the replacement Valve Assembly.
3. Tighten the replacement Valve Assembly to 50 inch-pounds.



**OHIO WILLOW WOOD**

*free the body...free the spirit®*

15441 Scioto Darby Road  
Mt. Sterling, OH 43143

phone 740.869.3377 / 800.848.4930 / fax 740.869.4374

PN-1772-B 1 NOV 2005

[www.owwco.com](http://www.owwco.com)